

Name Site & Shelter

Service No. 234

Address 30 Barberrry Road

Location

Kind of Pipe

Size

Size of Main

Repair ~~or removal~~ - New Service

*Conn. 12-3-51*

Location

Date	Material	Amount	Total	Date	Amount
11-2-51	Labor	1 65	1 65	<i>4-25-51 Deposited</i>	10 00
	10% Overhead		17	<i>9-23-52 Paid</i>	6 11
	24'-3/4" Copper Tubing @.326		7 82		16 11
	1-3/4" Cx 1/2" I.W.H. S&W		4 00		
	1-3/4" Cx 3/4" E Union (3 pts)		1 72	11-2-51	No Charge
	1 Hr. Trucking		75		Labor
	Total		16 11		2 39
	Trench Dug By Owner				24'-3/4" Copper Tubing @.326
	Pipe Supplied And Laid By Owner				7 82
	Labor				1-3/4" C Corp Cock
					4 33
					1-3/4" cx 3/4" C Curb Cock
					4 67
					1-Box & Rod
					4 68
					1-1/2" Offset Tail Piece
					50
					1-1/2" Straight Tail Piece
					50
					1 Hr. Trucking
					75
					Total
					25 64

The Daily Press, Boston

*bill sent 12-3-51*

W.S. For # 30

