

Name Site & Shelter
Address 34 Barberby Road

Service No. 234

Kind of Pipe Location Size Size of Main
~~Repair~~ ~~General~~ - New Service *Com. 10-3-51* Location

Date	Material	Amount	Total	Date	Amount
11-5-51	Labor	1 65	1 65	9-25-51 Deposited	10 00
	10% Overhead		17	12-3-51 Refunded & credited to bal. due on # 306	(3 43)
	1-3/4" Cx 1/2 I.W.H. S&W		4 00		6 57
	1 Hr. Trucking		75	No Charge	
	Total		6 57	11-5-51 Labor	3 93
	Trench Dug By Owner			49' - 3/4" Copper Tubing @ .326	15 97
	Pipe Supplied & Laid By Owner			1-3/4" C Corp Cock	4 33
				1-3/4" Cx 3/4" C Curb Cock	4 67
				1 Box & Rod	4 68
				1-1/2 Straight Tail Piece	50
				1-1/2 Offset Tail Piece	50
				1 Hr. Trucking	75
	Labor			Total	35 33

34

89.5

63.2

