

WATER SERVICE RECORD

Name Frank Johnson

Service No. 149

Address 336 Bedford Street

Location

Repair/Replace - New Service (House Moved Back)

Comm 12-18-61


Date	Material	Amount	Total	Date		Amount
11-9-61	Labor	4.19		10-3-61	Deposit	100.00
	10% O.H.	.42	4.61	12-18-61	Refund	34.95
112	3/4" Copper tubing @.42		47.04			65.45
3	3/4" C 3 part unions @2.41		7.23	10/30/48	10' 3/4 COPPER	
1	3/4" C x 1/2 I.W.H. Stop & Waste		6.17		1 3/4 CORP	
			65.05		1 3/4 CURB	
					1 Box & Rod	
					<del>that</del>	
				10/22/62	Broken by Const.	
					40' 3/4 Copper	
					1 3/4 CURB	

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here



Connection made in ..... Street. Work completed .....

Remarks: .....  
.....  
.....