

Name K. V. Wolsey
 Address 545 Bedford Street

Service No. 130
 # 7452

Location 545 Bedford Street

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~XXXXXX~~ New Service

Com. 8-15-49

Location

Date	Material	Amount	Total	Date	Amount
June 15, '49	Labor	6 95	6 95	July 11, '49	40 00
	10% Overhead		70	Oct 3, '49	7 96
	12' - 3/4" Copper Tubing @.24	2 88			47 96
	1 - 3/4" C x 1/2" I.W.H. S&W	3 29		June 15, '49	36 75
	1 - 3/4" C x 3/4" C Union	1 39		38' - 3/4" Copper Tubing @.24	9 12
	Trucking 1 hr.		75	1 - 3/4" C Corp-cock	3 15
	Patching 32 x 3		32 00	1 - 3/4" C x 3/4" C Curb-cock	3 85
			47 96	1 - Box & Rod	3 95
				1 - 1/2" Offset Tail Piece	37
				1 - 1/2" Straight Tail Piece	37
				Compressor 4 hrs. @1.75	7 00
				Trucking 1 hr.	75
	Labor				65 31

