Name Mr. Donald Wilson

Address 33 Bloomfield Street, Lexington

Service No. 3111

Location

Kind of Pipe

Size

Size of Main

Repair Renewal Service

Location

Date	Material	Amount		Total		Date		Amount	
	P. 40' 1" G.W.I. Pipe @.20	8	00						
	1 Ell		15			July	29 Cash	31	17
	1 Space Nipple		15						
	1 Stop & Waste	2	75						
	Trucking	1	50	12	55				
	Total Labor			27	10				
	Overhead 15%			4	07				
				31	17				
	Labor								
Apr. 30	20 Hrs. @ .55	11	00						
	1 Hr. @ .60		60						
May 10	26 Hrs.	14	30						
	2 Hrs. @ .55.60	1	20						
		27	10						

The Bailey Press, Boston

14.3
14.4