

WATER SERVICE RECORD

2337  
Service No. 12

Name Joseph Cataldo

Address 52 Bow Street

Location

Repair ~~General~~ New Service

*Com. 5-3-54*


Date	Material	Amount	Total	Date	Amount
4/13/54	Labor	1 85		4-9-54	25 00
	10% Overhead	19	2 04	5-4-54	(2 45
	72' - 3/4" Copper tubing @ .35	25 20		6-9-54	6 26
	1 - 3/4" C x 1/2 I.W.H. stop & waste	4 00			<u>33 71</u>
	1 - 3/4" C x 3/4" C. Union 3 pts.	1 72		4/13/54	Labor
	1 hr. trucking		75		1 85
			33 71		8' - 3/4" Copper tubing @ .35
					2 80
					1 - 3/4" C. corp-cock
					4 33
					1 - 3/4" C x 3/4" C. curb-cock
					4 67
					1 box and rod
					3 90
					1 - 1/2 straight tail piece
					50
					1 - 1/2 offset tail piece
					50
					1 hr. trucking
					75
					<u>19 30</u>

*cont 5-4-54*

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**  
**WATER DIVISION**

Sketch of Service Here



Connection made in ..... Street.      Work completed .....

Remarks: .....  
.....  
.....