

WATER SERVICE RECORD

Name Benjamin Gott

Service No. 76

4819

Address 32 Brandon Street

Location Lexington

Repair ~~Renewal~~ New Service

Com. 7-28-52


Date	Material	Amount	Total	Date	Amount
6/5/52	Labor	1 63		5-1-52	
	10% Overhead	16	1 79	7-28-52	
	42' - 3/4" Copper tubing @ .3439		14 44	<i>Deposited</i> <i>174/1000</i> <u>NON CHARGE</u>	
	1-3/4" C x 1/2" I.W.H. Stop & Waste		4 00	6/5/52	Labor
	1 hr. trucking		75		1 63
			20 98	24' - 3/4" Copper tubing @ .3439	8 25
				1-3/4" C x 3/4" C. Union 3 pts.	1 72
				1-3/4" C x 3/4" C. Curb-cock	4 67
				1 Box and Rod	4 52
				1-1/2" offset tail piece	50
				1-1/2" straight tail piece	50
				1 hr. trucking	75
					<u>22 54</u>
	<u>WATER CHANGE TO NEW MAIN</u>				
9-22-64	1 3/4" Corp Cock				
	5' 3/4" Copper tubing				

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:

.....

.....