

Name Michael Scanlon

Service No. ~~48~~ 386

Address 33 Brandon St. c/o Kenego

# 580

Location 33 Brandon St.

# 121

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Location

Date	Material	Amount	Total	Date	Amount
	1 1" S. Nipple	15			
	1 S & W	2 75			
	Trucking	75	3 65		
	o 1 Hour Labor		60		
	Overhead 15%		9		
			4 34		
	Turning on water		3 00		
			7 34		
	<u>WATER CHANGE TO NEW MAIN</u>				
	1 3/4" Corp Cock				
	1 3/4" Union				
	5' 3/4" Copper tubing				
	Labor				
	7/13/94 Repair Leak on Copper 6" Front Corp				
	2 3/4 Copper				
	1 3/4 Comp unions				

Nov 30 Abate

3 00

Mar. 30 1927 - Cash

4 34

WATER CHANGE TO NEW MAIN

9-22-64

1 3/4" Corp Cock

1 3/4" Union

5' 3/4" Copper tubing

Labor

7/13/94 Repair Leak on Copper 6" Front Corp

2 3/4 Copper

1 3/4 Comp unions

