

WATER SERVICE RECORD

Name John E. Lundquist

Service No. 78

Address 62 Buckman Drive

Location Lexington

Repair ~~XXXXXX~~ - New Service

COM. 5-18-53

| Date   | Material                            | Amount | Total | Date    | Amount                                |
|--------|-------------------------------------|--------|-------|---------|---------------------------------------|
| 5/4/53 | Labor                               | 1 75   |       | 4-22-53 | Deposited 100 00                      |
|        | 10% overhead                        | 18     | 1 93  | 5-18-53 | Refunded 4 00                         |
|        | 48' - 3/4" Copper Tubing @ .34      |        | 16 32 |         | NON-CHARGE 26 00                      |
|        | 1-3/4" C. x 1/2 I.W.H. stop & waste |        | 4 00  | 5/4/53  | Labor 4 75                            |
|        | 1 Hr. Trucking                      |        | 75    |         | 10' - 3/4" Copper tubing @ .34 3 40   |
|        | Patching 3 x 3                      |        | 3 00  |         | 1-3/4" C. Curb-cock 4 33              |
|        |                                     |        | 26 00 |         | 1-3/4" C x 3/4" C. Curb-cock 4 67     |
|        | TRENCH DIG BY OWNER                 |        |       |         | 1-Box & Rod 3 90                      |
|        |                                     |        |       |         | 1-1/2 offset tail piece 50            |
|        |                                     |        |       |         | 1-1/2 straight tail piece 50          |
|        |                                     |        |       |         | 2 Hr. Littlefield Shovel @ 7.50 15 00 |
|        |                                     |        |       |         | 1 Hr. Trucking 75                     |
|        |                                     |        |       |         | <u>37 80</u>                          |

