

WATER SERVICE RECORD

Name Luongo

Service No. _____

Address Buckman Drive

Location Lexington, Mass.

~~Repair or Renewal~~ - New Service

Date	Material	Amount	Total	Date	Amount
	No Charge				
	15' - 1" Copper Tubing @.284		42 60		
	2 - 1"C x 1" I.I.H. S&W		4 48		
			<u>47 08</u>		
				6-17-50	Labor 24 45
					11' - 1" Copper Tubing @.284 31 24
					1 - 1" C Corp-cock 4 62
					1 - 1"C x 1"C Curb-cock 5 60
					1 - 1"C x 1" I Union (2pts) 1 13
					1 - 2 1/2" Clay Pipe 1/4 ft. long @5.39 21 56
					1 - Pit Cover and Frame 8 65
					1 - Box & Rod 3 35
					2 - 1" Straight Tail Pieces 1 00
					Littlefield Shovel 2 hrs. @ 7.00 14 00
					Trucking 1 hr. @.75 75
					<u>116 35</u>

