

Name ~~William Wiles~~

CLARK BR404

Service No. # 71001

8984

Address 176 Burlington Street

Lexington, Mass.

Location 176 Burlington Street

Kind of Pipe

Size

Size of Main

~~Repair-Renewal~~ New Service

Com. 8-23-48

Location

Date	Material	Amount	Total	Date	Amount
Jul. 16, '48	Labor	2 20	2 20	July 14 '48	55 00
	10% Overhead		22	July 20 '48	14 43
	86' - 3/4" Copper Tubing @.255	21 93		Non-Charge	40 57
	1 - 3/4" C x 1/2" I.W.H. S & W	3 15		Jul. 16, '48 Labor	4 40
	1 - 3/4" C x 3/4" C Union (3pts)	1 32		19' - 3/4" Copper Tubing @.255	48 45
	Trucking 1 hr. @.75	75		1 - 3/4" Corp-cock	3 00
	Patching 11 x 3	11 00		1 - 3/4" C x 3/4" C curb-cock	3 68
			40 57	1 - Box & Rod	3 55
	trench dug by owner.			1 - 1/2" Offset Tail Piece	30
	Labor			1 - 1/2" Straight Tail Piece	30
				Littlefield Shovel 2 hrs. @7.00	14 00
				Trucking 1 hr. @.75	75
					78 43

