

WATER SERVICE RECORD

#4168

Name Oscar W. Carlson

Service No. 76

Address 95 Burlington Street

#7541

Location

~~Repair-Renewal~~ New Service

Comm - 9-24-56

Date	Material	Amount	Total	Date	Amount
5/15/56	Labor	1 90		4-28-56	Deposit 25 00
	10% overhead	20	2 10	9-24-56	Paid \$ <u>5 61</u>
					<u>30 61</u>
47' 3/4"	Copper tubing @ .4850	22 80			
1	3/4 Cx ¹ / ₂ I W H stop & Waste	4 96			
1	hr trucking @ .75	75	28.51		NON CHARGE
			30 61	11' 3/4"	Copper tubing @ .4850 5 34
				1	3/4" C Core Cock 4 34
				1	3/4" C Curb Cock 5 94
				1	Box & Rod 4 62
				1 $\frac{1}{2}$	Straight tail piece 50
				1 $\frac{1}{2}$	Offset tail piece 50
					<u>23 14</u>
				* Paid by refund on S.H.C. #36	

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large rectangular area filled with a grid of small squares, intended for drawing a sketch of service.

Connection made in Street. Work completed

Remarks:

.....

.....