

WATER SERVICE RECORD

Name W. A. McLaughlin

Service No. 517

Address 98 Burlington Street

7674

Location

Repair ~~Renewal~~ New Service

Comm. 11-23-53

Date	Material	Amount	Total	Date	Amount
10/22/53	Labor	8 00		10-2-53 Deposited	60 00
	10% Overhead	80	8 80	11-23-53 Refunded	16 93
	40' - 3/4" Copper tubing	36 29	14 52	NOT STAGE	48 07
	1 - 3/8" Cr. I.W.K. stopwaste	4 00		10/22/53 Labor	8 00
	2 ars. Littlefield shovel	7.50	15 00	20' - 3/4" Copper tubing	36 29
	1 hr. trucking		75	1 - 3/4" C. curb-cock	4 38
			48 07	1 - 3/4" C. x 3/4" C. curb-cock	4 67
				1 box and rod	3 90
				1-1/2 straight tail piece	50
				1-1/2 offset tail piece	80
				2 ars. Littlefield shovel	7.50
				1 hr. trucking	75
					44 91

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 15 rows high, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....