

WATER SERVICE RECORD

Name John Yosgandes

Service No. 309

Address 11 Carville Ave.

Location Lexington

~~Repair/Removal~~ New Service COM. 12-8-52

Date	Material	Amount	Total	Date	Amount
11/17/52	Labor	1 63	1 63	11-10-52	Deposited 25 00
	10% overhead		16	12-8-52	Refunded (6 54)
	30' - 3/4" copper tubing@.34	10 20			NON CHARGE 18 46
	1 -3/4"C x 1/2 I.W.H.stop & waste	4 00		11/17/52	Labor 1 63
	1 -3/4"C. union		1 72	26' -3/4" copper tubing@.34	8 84
	1 hr. trucking		75	1 -3/4"C. corp-cock	4 33
			18 46	1 -3/4"C x 3/4"C.curb@cock	4 67
				1 box and rod	3 90
				1 -1/8 straight tail piece	50
				1 -1/2 offset tail piece	50
				1 hr. trucking	75
					25.12

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 20 rows high, intended for sketching service details.

Connection made in ..... Street: ..... Work completed .....

Remarks: .....  
.....  
.....