

WATER SERVICE RECORD

Name _____ Service No. _____

Address # # 53 Cliffe Avenue

Location # 58 Cliffe Avenue

Repair—Renewal—~~New Service~~ # 7429


Date	Material	Amount	Total	Date	Amount
4/30/54	35' 3/4" Copper 1 3/4" CX 1/2 l.w. H. stop + waste				
					(OUTSIDE)
				3/17/70	Labor 130 80
				3/19/70	" 94 14
				3/2-70	" 53 00
				125'	3/4" Copper pipe .79 98 75
				1	3/4" Union 3 05
				1	Box & Rod 5 10
				1/2	Ton cold patch 5.85 2 93
				6	Hrs. trucking 3.00 18 00
				10	Hrs. shovel 4.00 40 00
				3	Hrs. compressor 3.00 9 00
					454 77

DATE _____

TOWN OF LEXINGTON BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:
.....
.....