WATER SERVICE RECORD

Name ~~Site & Shelter~~ Service No.

Address 521 Concord Avenue

Location

~~Repair Renewal~~ New Service

Date	Material	Amount	Total	Date		Amount
					No Charge	
				11-30-51	Labor	2 57
					25'-3/4"Copper Tubing @.326	8 15
					1-3/4"C Corp Cock	4 33
					1-3/4"Cx3/4"C Curb Cock	4 67
					1- Box & Rod	4 68
					1 Hr. Trucking	75
	Trench Dug By Owner				Total	25 15

HP-8865

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

Connection made in ..... Street. Work completed .....

Remarks: .....

.....

.....