WATER SERVICE RECORD

Name Site & Shelter

Service No. 232

Address 542 Concord Avenue

Location

~~Repair~~ ~~Removal~~—New Service Com. 12-31-51

Date	Material	Amount	Total
11-29-51	Labor	1 49	1 49
	10% Overhead		15
	1-3/4"Cx½ I.W.H. S&W		4 00
	1 Hr. Trucking		75
	Patching 20x3		20 00
	Total		26 39
	Trench Dug By Owner		
	Pipe Supplied And Laid By Owner		

Date		Amount
9-25-51	Deposited	10 00
9-8-52	Paid	16 39
9-20-52	Paid	26 39
	No Charge	26 39
11-29-51	Labor	5 72
	28'-3/4" Copper Tubing @.326	9 12
	1-3/4"C Corp-Cock	4 33
	1-3/4"Cx3/4"C Curb-Cock	4 67
	1- Box & Rod	4 68
	1-½ Offset Tail Piece	50
	1-½ Straight Tail Piece	50
	4 Hr. Littlefield Shovel	28 00
	1 Hr. Trucking-	75
	Total	58 27

2-15-52

HP-8855

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

Connection made in ..... Street. Work completed .....

Remarks: .....

.....

.....