

WATER SERVICE RECORD

Name

Service No.

Address

~~569 Concord Ave~~ 569 Concord Ave

Location

Lexington

Repair ~~Renewal~~ - New Service


Date	Material	Amount	Total	Date	Amount
11/2/54	40' 3/4 COPPER 1 3/4 x 1/2 S + W				
					<u>NON CHARGE</u>
				4/15/52	Labor 3 02
				24' - 3/4" copper tubing @ .3439	8 25
				1 - 3/4" C. corp-cock	4 33
				1 - 3/4" C x 3/4" C. curb-cock	4 67
				1 box and rod	4 52
				1 hr. trucking	75
					25 54

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here



Connection made in ..... Street.                      Work completed .....

Remarks: .....  
.....  
.....