

WATER SERVICE RECORD

# 4278

Name Moore Realty Trust

Service No. 2

Address 6 Crawford Road

Location

Repair ~~XXXXXX~~ - New Service

Comm 5-4-59

Date	Material	Amount	Total	Date	Amount
3-9-59	Labor	3 76		3-5-59	50 00
	10% O. H.	38	4 14	5-4-59	13 90
63'	3/4" Copper Tubing @.3666		23 10		<u>36 10</u>
1	3/4" C x 1/2 I.W.H. Stop & Waste		5 81		
1	3/4" C 3 part Union		2 27		
1	Hr. Trucking @.75		75		
			36 10		

Deposit  
Retuned

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**WATER DIVISION**

Sketch of Service Here

A large rectangular area filled with a grid of small squares, intended for a hand-drawn sketch of water service details.

Connection made in ..... Street: ..... Work completed .....

Remarks: .....  
.....  
.....