

WATER SERVICE RECORD

#6537 # 3650

Name Ira Boynton

Service No. 208

Address Lot 204 Dane Road # 21 DANE RD.

Location

~~Repair-Remarks~~ - New Service

Comm. 12-9-57

Date	Material	Amount	Total	Date	Amount
9-25-57	Labor	12.19	.	9-24-57	Deposit \$50.00
	10% O.H.	1.22	13.41	12-2-57	Refund
	52' 3/4" Copper tubing @.375		19.50		\$488
	1 3/4" C x 1/2 I.W.H. Stop & Waste		4.96		\$4512
	1 hr. trucking @.75		.75		<u>NON CHARGE</u>
	1 hr. Town Shovel @ 6.50		6.50	5/4/57	Labor 4 29
			16.50	24' 3/4" Copper tubing @.4228	10 15
			45.12	1 3/4" C Corp Cock	4 64
				1 3/4" C Curb Cock	5 94
				1 Box & Rod	4 62
					<u>29 64</u>
				9-25-57	
				1 1/2 Straight tail piece	1 50
				1 1/2 Offset tail piece	.50
					<u>30.64</u>

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

15

Connection made in Street. Work completed

Remarks:
.....
.....