

WATER SERVICE RECORD

Name Belmont Realty Trust

Service No. 204

Address 2 Fairfield St.

Location

Repair-Renewal-New Service

Conn. 8-15-55

Date	Material	Amount	Total	Date	Amount
6/6/55	Labor	1 85			
	10% Overhead	19	2 04		
	30' - 3/4" Copper tubing	8 93	11 08	8-22-55	17 87
	1 - 3/4" Cr. I.W.F. stopwaste		4 00	8/6/55	
	1 hr. trucking		75		3 70
			17 87		
				8-21-55	
					3 12
					4 33
					4 37
					3 90
					50
					50
					75
					26 47

Trunk dug by owner.

No Deposit Paid

NON CHARGE

Labor

30' - 3/4" Copper tubing

1 - 3/4" C. curb-sock

1 - 3/4" C. x 3/4" C. curb-sock

1 box and rod

1 - 1/2 straight tail piece

1 - 1/2 offset tail piece

1 hr. trucking


8-15-55

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:

.....

.....