

WATER SERVICE RECORD

Name

Service No.

Address

68 Farmcrest Avenue

Location

Repair—Renewal—New Service

Date	Material	Amount	Total	Date	Material	Amount
10/18/50	42' 3/4" Copper					
	1 3/4" x 1/2" Valve					
					OUTSIDE	
				1985	2' 1" Copper	
					1" Corp	
					3/4" x 1" Reducer	
					26' 3/4" Copper	
					3/4" Coupling	
					+17' 3/4" Copper	
					3/4" Curb Cock	
					Box & Rod	

