

Name H. E. Samuelson

Service No. #3335  
3366

Address 143 Follen Road

Lexington, Mass.

Location 143 Follen Road

Kind of Pipe

Size

Size of Main

~~Repair & Removal~~ — New Service

Com. June 7, 1948

Location

Date

Material

Amount

Total

Date

Amount

Apr. 23, '48	Labor	2 95	2 95
	10% Overhead		30
	45' - 3/4" Copper Tubing @.255	11 48	11 48
	1 - 3/4" C x 1/2" I.W.H. S & W	3 15	3 15
	Littlefield Shovel 2 hrs. @ 7.00	14 00	14 00
	Trucking 1 hr. @.75		75
	Patching 8 x 3		8 00
			<u>40 63</u>

Apr. 18 '48	Deposited	50 00
June 10 '48	Refunded	7 37
	non-charge	<u>40 63</u>
Apr. 23, '48	Labor	6 10
	12' - 3/4" Copper Tubing @.255	3 06
	1 - 3/4" C x 3/4" C Curb-cock	3 68
	1 - 3/4" C Corp-cock	3 00
	1 - Box & Rod	3 50
	Littlefield Shovel 1 hr. @ 7.00	7 00
	Trucking 1 hr. @.75	75
	1 - 1/2" Offset Tail Piece	30
	1 - 1/2" Straight Tail Piece	30
		<u>27 69</u>

Labor

