

Name Frank Douglas
 Address 220 Follen Road
 Lexington, Mass.

Service No. *2-3*

279

Location 220 Follen Road

Kind of Pipe

Size

Size of Main

~~Repair - Renewal~~ New Service

Com. 11-8-49

Location

Date

Material

Amount

Total

Date

Amount

Oct. 12, '49	Labor	5 00	5 00
	10% Overhead		50
	52' - 3/4" Copper Tubing @.24	12 48	12 48
	1 - 3/4" C x 1/2" I.W.H. S&W	3 29	10 50
	Littlefield Shovel 1 1/2 hrs. @7.00	7 00	
	Trucking 1 hr. @.75		75
	Patching 25 x 3		25 00
			57 52

<i>Oct 12, 49</i>	<i>Deposited</i>	<i>9000</i>
<i>Nov 17 49</i>	<i>Refunded</i>	<i>3250</i>
	No Charge	57 52
Oct. 12, '49	Labor	7 50
	33' - 3/4" Copper Tubing @.24	7 92
	1 - 3/4" C Corp-cock	3 15
	1 - 3/4" C x 3/4" C Curb-cock	3 85
	1 - Box & Rod	3 75
	1 - 1/2" Offset Tail Piece	87
	1 - 1/2" S traight Tail Piece	87
	Littlefield Shovel 2 hrs. @7.00	14 00
	Trucking 1 hr. @.75	75
		41 66

*7/23/07 53' - 1" copper
 1 x 3/4 curb adpt.*

Labor

