

Name Richard O. Bramhall

Service No. 260

Address 17 Gleason Road

254

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Recessed~~ - New Service

Com. 12-3-51

Location

Date	Material	Amount	Total	Date	Material	Amount
10-31-51	Labor	4 22	4 22	10-22-51	<i>Deposited</i>	50 00
	10% Overhead		42	12-3-51	<i>Refunded</i>	71
	58' - 3/4" Copper Tubing @ .326	18 90	18 90			49 29
	1-3/4" Cx 3/4" I.W.H. S&W	4 00	4 00		no Charge	
	3 Hr. Littlefield Shovel @ 7.00	21 00	21 00	10-31-51	Labor	4 22
	1 Hr. Trucking		75		8' - 3/4" Copper Tubing @ .326	2 60
	Total		49 29		1-3/4" C. Corp-Cock	4 33
					1-3/4" Cx 3/4" Curb Cock	4 67
					1-3/4" Cx 3/4" C Union (3 pts)	1 72
					1 Box & Rod	4 68
					1-1/2" Offset Tail Piece	50
					1-1/2" Straight Tail Piece	50
	Labor				1 Hr. Littlefield Shovel	7 00
					1 Hr. Trucking	75
					Total	30 97

