

Name Morris Malcolm

Service No.

67 3306

Address 46 Gleason Road

#2902

Leviston, Mass.

Location 46 Gleason Road

Kind of Pipe

Size

Size of Main

~~Report Received~~ - New Service

Location

Date	Material	Amount	Total	Date	Location	Amount
Jul. 15, '47	Labor	10 75	10 75	July 10, '47	Deposited	50 00
	10% Overhead		1 08	Sept 25, '47	Refunded	2 36
	33' - 3/4" Copper Tubing @ .27		8 91		Non-Charge	47 64
	1 - 3/4" C x 1/2" I.V.H. S & W		3 15	Jul. 15, '47	Labor	40 28
	Patching 23 x 3		23 00	16	"	8 23
	Trucking 1 hr. @ .75		75	29' - 3/4" Copper Tubing @ .27		7 83
			47 64	1 - 3/4" Corp-cock		3 00
				1 - 3/4" C x 3/4" C Curb-cock		3 68
				1 - 1/2" Straight Tail Piece		30
				1 - 3/8" Offset Tail Piece		30
				Trucking 1 hr. @ .75		75
				1 - Box & Rod		4 26
	Labor					68 63

