

WATER SERVICE RECORD

Name Ampolo Const. & Eng. Corp.

Service No. 57

Address 5 Graham Road

Location

Repair—Renewal—New Service

Date	Material	Amount	Total	Date	Amount
4/6/56	Labor	1 95		4-5-56	Deposit # 40 00
	10 % overhead	19	2 14	8-6-56	Refund 10 32
	45' 3/4" copper tubing @.4850		21 83		<u>NON CHARGES</u> 29 68
	1 - 3/4" C x 1/8" I.W.H. stop&waste		4 96	10' 3/4" copper tubing @.4850	4 85
	1 hr. trucking @.75		75	1 - 3/4" C Corp Cock	4 34
			29 68	1 - 3/4" C Corp Cock	5 94
				1 Box & Rod	4 62
				1 1/2 straight tail piece	50
				1 1/2 offset tail piece	50
					<u>22 70</u>

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....