

Name Mr. Jenny

WATER SERVICE RECORD

Service No.

6195
161

Address 2 Great Rock Road

Location Lexington

~~Repair~~ New Service

Case 11-3-52

Date	Material	Amount	Total	Date	Amount
10/9/52	Labor	1 80		8-5-52 Deposited	60 00
	10% Overhead	18	1 98	11-5-52 Refunded	16 59
	52' - 3/4" Copper tubing @ .32		17 68	NON CHARGE	43 41
	1 - 3/4" C x 1/2 I/W.H. stop & Waste		4 00	10/9/52 Labor	7 77
	1 hr. trucking		75	21' - 3/4" Copper tubing @ .34	7 14
	patching 19 X 3		19 00	1 - 3/4" C. Corp-cock	4 33
			43 41	1 - 3/4" C x 3/4" C. curb-cock	4 67
				1 box and rod	3 90
	TRENCH DUG BY OWNER			1 - 1/2 straight tail piece	50
				1 - 1/2 offset tail piece	50
				3 hr. Littlefield shovel	21 00
				1 hr. trucking	75
					50 56

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of approximately 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....