

WATER SERVICE RECORD

Name **Caryl Realty Trust**

Service No. 90

Address **6 Great Rock Road**

Location

~~REPAIR~~ ~~REPAIR~~ New Service

Conn 76-59


Date	Material	Amonst	Total	Date	Amount
5-16-59	Labor	3 70		6-13-59	Deposit 35 00
	10% O. H.	37	4 07	7-6-59	Returned 7 46
	3 1/4' 1" Copper Tubing @.4731		16 09		27 54
	1 1" C x 1 IWH Stop & Waste		6 63		<u>NON CHARGE</u>
	1 Hr. Trucking @.75		75	5-16-59	Labor 32 55
			27 54		26' 1" Copper Tube @.4731 12 30
					1 1" C Corp C&Ck 7 10
					1 1" C Curb C&Ck 7 64
					1 Box & Rod 5 00
					1 1" Straight Tailpiece 93
					1 1" Offset Tailpiece 93
					<u>66 45</u>

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:
.....
.....