

WATER SERVICE RECORD

Name Benjamin Franklin Homes

Service No.

5529
7007
259

Address L Grimes Road

Location

Repair—Renewal—New Service

Comm 12-14-59


Date	Material	Amount	Total	Date	Amount
10-20-59	Labor	15 62		10-15-59	Deposit 50 00
	10% C. H.	1 56	17 18	1-13-60	Paid 17 16
	87' 3/4" Copper tubing @.42		36 54		62 16
	1 3/4" C x 1/2 I.W.H. Stop & Waste	5 88			NON CHARGE
	3 3/4" C 3 part Unions @2.27	6 81		10-6-59	Labor 3 62
	1 Hr. Trucking @.75		75	35'	3/4" Copper tubing @/41 14 35
			67 16	1	3/4" C Core Cock 4 64
				1	3/4" C Curb Cock 5 94
				1	Box & Rod 5 00
				1	Hr. Trucking 75
					34 30
				10-20-59	1 1/2 Straight Tailpiece 50
					1 1/2 Offset Tailpiece 50
					35 30

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:
.....
.....