

WATER SERVICE RECORD

Name Busa Bros.

Service No. 37

Address 7 Melrose Avenue

Location

~~Water~~ ~~XXXXXX~~ New Service

*Amor 5-4-59*

Date	Material	Amount	Total	Date	Amount
4-15-59	Labor	7 60		4-9-59	50 00
	10% O. H.	76	8 36	5-11-59	15 99
	52' 3/4" Copper Tubing @.3666		19 06		34 01
	1 3/4" C x 1/2 I.W.H. Stop & Waste	5	84		NON CHARGE
	1 Hr. Trucking @.75		75	4-15-59	Labor 9 57
			34 01		37' 3/4" Copper Tube @.3666 13 56
					1 3/4" C Corp Cock 4 64
					1 3/4" C Curb Cock 6 03
					1 Box & Rod 5 00
					1 1/2 Straight Tailpiece 50
					1 1/2 Offset Tailpiece 50
					1 Hr. Town Shovel @6.50 6 50
					46 50
					<i>* Applied to sheet 18</i>

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in ..... Street.                      Work completed .....

Remarks: .....  
.....  
.....