

WATER SERVICE RECORD

Name **Frank A. Napoli**

Service No. **57**

Address **21 Middle St.**

(pit)

Location

~~Repair~~ **New Service**

Com. 4-27-53

Date	Material	Amount	Total	Date	Amount
4/2/53	Labor	25 57		3-23-53 Deposited	75 -
	10% Overhead	2 56	28 13	4-27-53 Refunded	(24 81)
	4' - 2" C.L. Pipe @.8152		3 26		NON CHARGE
	1 - 2" x 1 1/2" L.L. Coupling		1 85		50 19
	1 - 1 1/2" C.L. Nipple 6" long		45	3/31/53 Labor	38 22
	1 hr. Littlefield shovel @7.50	7 50	7 50	25' - 1" Copper tubing @.3997	9 99
	2 hr. Hough Loader @3.00	6 00	6 00	4 - 1" C. corp-cock @5.61	22 44
	patching 3 x 3		3 00	1 - 2" T.H. Gate Valve	12 50
			50 19	1 - 10" x 2" I. 4 way branch	19 38
				2 - 2" C.L. Nipples 6" Long @.65	1 30
				2 - 2" x 1 1/2" L. L. Couplings @1.85	3 70
				2 - 1 1/2" C. L. Nipples 6" long @.45	90
				300 White Brick @ 22 per M	3 30
				1 pit cover and frame	9 88
				2 hrs. Littlefield shovel @7.50	15 00
				2 hrs. trucking @.75	1 50
					<u>138 11</u>

