

WATER SERVICE RECORD

Name

Service No.

Address 11 Mountain RD

Location

Repair—Renewal—New Service Redmond

| Date | Material | Amount | Total | Date | Exist- INSIDE | Amount |
|---------|------------------------------|--------|-------|---------------|------------------------|-------------|
| 3/23/06 | 204' 1" Copper | | | 11/8/79 | 384' 2" K-Copper | |
| | 39' 1" Wye To Curb | | | | 1 8"x2" Service Saddle | |
| | 3 1" UNIONS | | | | 1 2" COPPERATION | |
| | 1 1" Curb STOP | | | | 1 2" oriseal Curb | leaks by 06 |
| | 1 2" RD Rdway Box | | | | out | |
| | 1 2"x1" Wye | | | MAINT to curb | 19'-2" Copper | |
| | | | | | RD way box | |

