

WATER SERVICE RECORD

Name Park Department *(Park Drive)*

Service No. 106

Address Stand Pipe on 2" Line

Location

Repair—~~Renewal~~ ~~New~~ Service Com. 8-6-51

Date	Material	Amount	Total	Date	Amount
6-28-50	Labor	2 60	2 60	<i>No Deposit pd. 8-30-51</i>	17 55
	10% Overhead		26		
	5' - 2" C. L. Pipe		3 65		
	1 - 2" Galv. Elbow		1 50		
	1 - 2" x 1 1/2" L. L. Tee		1 73		
	1 - 2" Plug		90		
	1 - 1"C x 1" C.W.H. Stop & Waste		5 12		
	1 - 1" x 3/4" Brass Bushing		56		
	1 - 3/4" x 1/2" Brass Bushing		48		
	Trucking 1 hr. @ .75		75		
			17 55	<i>bill sent 8-6-51</i>	

