

## WATER SERVICE RECORD

# 329

Name Moore Realty Trust

Service No. 119

Address 7 Park Street

Location

~~REPAIRS~~ — New Service

Com. 6-13-55

Date	Material	Amount	Total	Date	Amount
5/4/55	Labor	3 45		5-3-55	50 00
5/5/55	"	3 45	6 90	6-13-55	5 68
	10% overhead		69		44 32
	46' - 3/4" copper tubing@.3693	16 98		5/5/55 Labor	3 45
	1 - 3/4" C x 1/2 I.W.H. stop & waste	4 00		27' - 3/4" copper tubing@.3693	9 97
	2 hrs. Littlefield shovel@	7.50	15 00	1 - 3/4" C. corp-cock	4 33
	1 hr. trucking		75	1 - 3/4" C. curb-bock	4 67
			44 32	1 box and rod	3 90
				1 - 1/2 straight tail pc.	50
				1 - 1/2 offset tail pc.	50
				1 hr. Littlefield shovel	7 50
				1 hr. trucking	75
					35 57

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here

A large rectangular grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in ..... Street.      Work completed .....

Remarks: .....

.....

.....