

## WATER SERVICE RECORD

# 815

Name Holiday Homes

Service No. 154

Address 17 Partridge Road

Location Lot #84 Sta 11/91

Repair ~~Work~~ New Service

Wo # 7016

Comm 2-26-62

Date	Material	Amount	Total	Date		Amount
1-10-62	Labor	13.11		12-29-61	Deposit	65.00
	10% O.H.	1.31	14.42			
	100' 3/4" Copper tubing @.42		42.00			
	1 3/4" C x 1/2 I.W.H. Stop & Waste		6.17			
	1 3/4" C 3 part union		2.41	8/1/61	Labor	7 25
			65.00		23' 3/4" Copper tubing @.42	9 66
					1 3/4" C Corp Cock	4 91
					1 3/4" C Curb Cock	6 28
					1 Box & Rod	4 90
						33 00
					1 1/2 Straight tailpiece	.50
					1 1/2 Offset tailpiece	.50
						34.00

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here

A large grid for sketching service details, consisting of 20 columns and 15 rows of small squares.

Connection made in ..... Street.                      Work completed .....

Remarks: .....

.....

.....