

WATER SERVICE RECORD

4869

Name Holiday Homes, Inc.

Service No. 92

Address 8 Partridge Road

Location Lot #63 Sta 5 / 86

~~REPAIR SERVICE~~ - New Service WO # 7460

Comm 12-1-62

Date	Material	Amount	Total	Date	Amount	
8/2/61	Labor	4 10		7-12-62	Deposit	75 00
	10% O.H.	41	4 51	10-2-62		20 08
	14' 3/4" Copper Tubing @ .42		5 88			95 08
	1 Hr. Trucking @ 3.00		3 00			
	BILL WHEN CONNECTED		13 39	8/2/61	Labor	1 89
7/12/62	Labor	9 72			6' 3/4" Copper Tubing @ .42	2 52
	10% O.H.	97	10 69		1 3/4" C Corp Cock	4 91
	130' 3/4" Copper Tubing @ .42		54 60		1 3/4" C Curb Cock	6 28
	1 3/4" Cx 1/2 IWH Stop & Waste		6 17		1 Box & Rod	4 90
	3 3 Part Unions @ 2.41		7 23			20 50
	1 Hr. Trucking @ 3.00		3 00		1 1/2 Straight Tailpiece	50
	REPAIR SERVICE CHARGES		95 08		1 1/2 Offset Tailpiece	50
						81 50

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....