

WATER SERVICE RECORD

Name

Service No.

Address 60 Paul Revere Road

Location Lexington

Repair ~~Renewal~~ - New Service

Date	Material	Amount	Total	Date	Amount
10-27-52					
	50' 3/4" Copper				NON CHARGE
	1 3/4" C. X 1/2 I.W.H. Stop + Waste			5/26/52	Labor 9 06
					30' - 3/4" Copper tubing @ .326 9 78
					1 - 3/4" C. Corp cock 4 33
					1 - 3/4" C x 3/4" C. curb-cock 4 67
					1 box and rod 4 68
					2 hrs. Littlefield shovel 14 00
					1 hr. trucking 75
				9-19-57	Repair - Broken by Contractor 47 27
					4' 3/4" Copper
					1 3/4" 3 Part Union
					1 3/4" Style 88 Coupling
					1 3/4" C. Curb Cock

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large rectangular area filled with a grid of small squares, intended for sketching or drawing service details. The grid consists of approximately 20 columns and 20 rows.

Connection made in Street. Work completed

Remarks:

.....

.....