

## WATER SERVICE RECORD

1419

Name Ralph Frissore

Service No.

208

Address 70 Paul Revere Road

Location

~~Repair~~ ~~Renewal~~ New Service

Comm 12-31-58

Date	Material	Amount	Total	Date	Amount	
10-8-58	Labor	3.70		10-6-58	Deposit	35.00
	10% O.H.	.37	4.07	12-31-58	Refund	6.85
47'	3/4" Copper tubing @.37		17.39			28.25
1	3/4" C x 1/2 I.W.H. Stop & Waste		5.84		NON CHARGE	
1	hr. Trucking @.75		.75		Labor	3.22
			28.05			
				31'	3/4" Copper tubing @.37	11.47
				1	3/4" C Corp Cock	4.64
				1	3/4" C Curb Cock	6.03
				1	Box & Rod	5.00
				1	1/2 Straight tailpiece	.50
				1	1/2 Offset tailpiece	.50
						31.36

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**WATER DIVISION**

Sketch of Service Here

A large rectangular grid of graph paper, consisting of approximately 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in ..... Street.      Work completed .....

Remarks: .....  
.....  
.....