

WATER SERVICE RECORD

Name Benjamin Franklin Homes, Inc.

Service No. 92

Address 18 Peacock Farm Road

#1918

Location Lot 22

~~Repair~~ ~~Renewal~~ - New Service

Service was in to curb.

Date	Material	Amount	Total	Date	Amount	
5/18/56	Labor	10 40		5-11-56	Deposit	\$75 00
	10% overhead	1 04	11 44	8-6-56	Refund	25 10
	50' - 3/4" Copper tubing @ .4850	24 25			NON CHARGE	49 90
	1 - 3/4" Cx 1/2" I.W.H. Stop & Waste	4 96	5/18/56	Labor	10 40	
	1 hr. trucking		75	1 - 1/2" Straight tailpiece	50	
	1 hr. Littlefield Shovel		8 50	1 - 1/2" Offset tailpiece	50	
			49 90	1 hr. Littlefield Shovel	8 50	
					19 90	
				10-13-54	Labor	4 98
					10' 3/4" Copper tubing @ .35	3 50
					1 3/4 G corp cock	4 33
					1 3/4 G curb Cock	4 67
					1 Box & Rod	3 90
					1 hr. Trucking	75
						42 03

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....