

WATER SERVICE RECORD

Name Benjamin Franklin Homes, Inc.

Service No. 93

Address 19 Peacock Farm Road

Location Lot 18

Comm. 11-19-56

~~Repair~~ - New Service

Service was in to curb

Date	Material	Amount	Total	Date	Amount	
6/11/56	Labor	12 07		5-11-56	Deposit	75 00
	10% overhead	1 23	13 30	11-19-56	Refund *	19 77
	70' - 3/4" Copper tubing @ \$.4850	33 95			NON CHARGE	55 23
	1 - 3/4Cx 1/2 I.W.H. Stop & Waste		4 96		1 - 1/2 Straight tailpiece	50
	1 hr. trucking		75		1 - 1/2 Offset tailpiece	50
	1 Union (3 part)		2 27			1 00
			55 23	10-13-54	Labor	4 97
					22' 3/4" Copper tubing @.35	7 70
					1 3/4" Copper stop cock	4 33
					1 3/4" G curb cock	4 67
					1 box & rod	3 90
					1 hr. Trucking	75
					* #1.61 applied to W.H.C #2	27 32

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....