

WATER SERVICE RECORD

#5061

Name Leeland Construction Company

Service No. 89

Address 11 Pine Knoll Road

Location

~~Repair - Renovat~~ - New Service

Comm. 9-3-57

Date	Material	Amount	Total	Date	Amount
5/11/57	Labor	18 30		5-10-57	Deposit \$100 00
	10% overhead	1 83	20 13	9-3-57	Refund 43 27
	50' - 3/4" Copper tubing @ .4228	21 14			<u>NON CHARGE</u> \$ 56 73
	1 - 3/4" Cx 1/2 I.W.H. Stop & Waste	4 96		Labor	20 12
	1 hr. Trucking		75	10' - 3/4"	4 23
	1 1/2 hrs. Town Shovel @ 6.50		9 75	1 - 3/4" C. Curb Cock	5 94
			56 73	1 - 3/4" C. Corp Cock	4 64
				1 Box & Rod	4 62
				1 - 1/2 Straight tailpiece	50
				1 - 1/2 Offset tailpiece	50
				1/2 hr. Town Shovel @ 6.50	3 25
					43 80

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large rectangular grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....