

## WATER SERVICE RECORD

Name Park Dept.

Service No.

Address Pleasant Street Island

Location

Repair—Renewal—New Service

Date	Material	Amount	Total	Date	Amount	
7-20-60	Labor	21.53				
7-21-60	" "	42.69	64 22			
	10% O.H.	6 42	70 64			
7'	3/4" Copper tubing@.42		2 94		NON CHARGE	
1	3/4" Cx3/4 I.W.H. Stop & Waste		5 84	7-20-60	Labor	7.21
1	3/4" Close Nipple Brass		70		3' 3/4" Copper tubing @.42	1.26
2	3/4x3/4 2 Part Union@1.24		2 48		1 3/4" C Corp Cock	4.91
6	Basin blocks		1 64		1 3/4" C Curb Cock	6.28
2	3/4"x1/2 Brass Bushings@.64		1 28		1 Box & Rod	4.90
1	Manhole cover & frame		35 00		1/2 hr. Town Shovel @6.50	3.25
1 1/2	Hr. Town shovel@6.50		9 75			27.81
1	Hr. Trucking@3.00		3 00			
			133 27			

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in ..... Street. Work completed .....

Remarks: .....

.....

.....