

WATER SERVICE RECORD

Name Joseph Silva

Service No. 139

Address 61 Reed Street (pit meter)

Location Lexington

~~Water~~ New Service

Com. 9.29.52

*This service is discontinued as of 6-4-54. This pit was taken out and the meter is in the house - # 5 Sunny Knoll Terrace*

Date	Material	Amount	Total	Date	Amount
8/23/52	Labor	65 48		7-11-52 Deposited	350 00
	10% Overhead	6 55	72 03	9-29-52 Re-funded	69 89
	350' - 1" Copper tubing @ .3997		139 90		280 11
	1 - 1" C x 1" I.W.H. stop & waste	6 80			
	1 - 1" x 3/4" red bushing		59		
	4 - 1" C x 1" C. Union 3pts @ 2.26	9 04			
	6 hrs. Littlefield shovel @ .7	42 00			
	3 hrs. Allis Chalmers @ .3	9 00			
	1 hr. trucking		75		
			280 11		
				8/23/52 Labor	10 00
				17' - 1" Copper tubing @ .3997	6 79
				1 - 1" C. Corp-cock	5 61
				1 - 1" C x 1" C. curb-cock	6 80
				1 - 3/4" offset tail piece	50
				1 - 3/4" straight tail piece	50
				500 cement brick @ 20. per M	10 00
				1 pit cover & frame	8 71
				1 hr. Littlefield shovel	7 00
				1 hr. trucking	75
					56 66

*This service is now # 5 Sunny Knoll Terrace*

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in ..... Street.      Work completed .....

Remarks: .....

.....

.....