

WATER SERVICE RECORD

Name **William G. Mason**

Service No. **109**

Address **6 Rockville Ave.**

Location **Lexington, Mass.**

Repair—Renewal—New Service

*Com. 7-28-52*

Date	Material	Amount	Total	Date	Amount
7/8/52	Labor	5 80		6-11-52	25 -
	10% Overhead	58	6 38	7-28-52	9 08
	70'-3/4" Copper tubing@.3439	24 07			NON CHARGE
	1-3/4" C x 1/2 I.W.H.Stop&Waste	4 00		7/8/52	Labor
	1-3/4" C x 3/4" C. Union 3 pts.	1 72			15' - 3/4" Copper tubing@.3439
	3 hrs. Littlefield Shovel	21 00			1-3/4" C. Corp-cock
	1 hr. trucking	75			1-3/4" C x 3/4" C. Curb-cock
	*Patching 8 X 3	8 00			1 Box and rod
			65 92		1-1/2 offset tail piece
					1-1/2 straight tail piece
					2 hrs. Littlefield shovel
					1 bag Rockwool
					1 hr. trucking
					41 61

\* Item of st. patching - \$8.00 - abated and money refunded on 9-2-52. as work was done by Private Painter making total refund \$17.08

