

WATER SERVICE RECORD

Name **Bob Davis, Inc.**

Service No. **114**

Address **29 Roosevelt Road**

2790

Location **Lexington**

~~Repair~~ **New Service COM. 9/8/52**

Date	Material	Amount	Total	Date	Amount
7/26/52	Labor	1 63		6-25-52 Deposited	40 00
	10% overhead	16	1 79	9-10-52 Refunded & credited to Bill. dup on W.A.C. 188	19 68
	37' - 3/4" copper tubing@.326	12 06	12 06	<u>NON CHARGE</u>	20 32
	1 - 3/4" C x 1/8 I.W.H. stop & waste	4 00	4 00	7/26/52 Labor	3 67
	1 - 3/4" C x 3/4" C. union 3 pts.	1 72	1 72	18' - 3/4" copper tubing@.326	5 87
	1 hr. trucking		75	1 - 3/4" C. corp-cock	4 33
			20 32	1 - 3/4" C x 3/4" C. curb-cock	4 67
				1 box and rod	4 68
	<u>TRENCH DUG BY OWNER</u>			1 - 1/8 offset tail piece	50
				1 - 1/8 straight tail piece	50
				1 hr. Littlefield shovel	7 00
				1 hr. trucking	75
					<u>31 97</u>

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....