

WATER SERVICE RECORD

Name Leeland Construction

Service No. 130

Address 6 Ross Road Lexington 73, Massachusetts

Location

~~REPAIR~~ New Service

Comm 11-9-59

Date	Material	Amount	Total	Date	Amount
8-4-59	Labor	3.44		6-17-59	25.00
	10% O.H.	.34	3.78	11-9-59	3.98
				11-9-59	3.04
114	3/4" Copper tubing @.41		46.74		34.41
1	3/4" C x 1/2 I.W.H. Stop & Waste		5.84		NON CHARGE
1	3/4" C 3 part union		2.30	8/7/58	
1	hr. Trucking @.75		.75	25' 3/4" Copper Tubing @ 37	9.25
			59.41	1 3/4" C CorpCock	4.64
				1 3/4" C Curb Cock	6.03
				1 Box & Rod	5.00
					24.92
				1 1/2 Straight tailpiece	.50
				1 1/2 Offset tailpiece	.50
					25.92

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....