

## WATER SERVICE RECORD

Name Benjamin Franklin Homes

Service No. 240

Address Lot 8 ~~Fifth Street~~ Rumford Avenue

Location 11 Rumford Road

~~Repair - Renewal~~ - New Service

Comm. 2/16/59

Date	Material	Amount	Total	Date	Amount
11/7/58	Labor	3 91		11/7/58	# 75 00
	10% overhead	39	4 30	2/16/59	Refund 26 69
	95' - 3/4" Copper tubing @	.37	35 15		# 48 31
	1 - 3/4" Cx $\frac{1}{2}$ I.W.H. Stop & Waste		5 84		<u>NON CHARGE</u>
	1 - 3/4" C. Union (3 part)		2 27	11/2/56	Labor 1 90
	1 hr. Trucking		75	16' 3/4" Copper tubing @ .4396	7 03
			48 31	1 3/4" C Corp Cock	4 64
				1 3/4" C Curb Cock	5 94
				1 Box & Rod	4 62
				1 $\frac{1}{2}$ Straight Tail Piece	50
				1 $\frac{1}{2}$ Offset Tail Piece	50
				1 Hr. trucking @ .75	75
					25 88

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in ..... Street.                      Work completed .....

Remarks: .....  
.....  
.....