

WATER SERVICE RECORD

Name Benjamin Franklin Homes

Service No. 241

Address 12 Rumford Road

Location Lot 4B

-Repair--Renewal--New Service

Comm. 2/16/59

Date	Material	Amount	Total	Date		Amount
11/8/58	Labor	3 91		11/7/58	Deposit	75 00
	10% overhead	39	4 30	2/16/59	Refund	41 91
	60' - 3/4" Copper tubing @ .37		22 20		NON CHARGE	\$ 33 09
	1 - 3/4" Cx 1/2 I.W.H. Stop & Waste		5 84	10/8/57	Labor	4 19
	1 hr. Trucking		75	20' - 3/4" Copper tubing		7 50
			33 09	1 3/4" C Corp Cock		4 64
				1 3/4" C Curb Cock		5 94
				1 Box & Rod		4 62
				1 Hr. Trucking @ .75		75
						27 64
				1 - 1/2 Straight tailpiece		50
				1 - 1/2 Offset tailpiece		50
						28 64

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of approximately 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....