

WATER SERVICE RECORD

Name Benjamin Franklin Homes

Service No. 16

Address 5 Rumford Road

Location

~~Repair~~ ~~Repair~~ ~~Repair~~ New Service

Comm 5-4-59

Date	Material	Amount	Total	Date		Amount
4-3-59	Labor	22.96		4-1-59	Deposit	50.00
	10% O.H.	2.30	25.26	5-12-59	Prd	17.37
	75' 3/4" Copper tubing @.3666		27.50		NON CHARGE	67.57
1	3/4" C x 1/2 I.W.H. Stop & Waste		5.84	4-3-59	Labor	3.06
1	3/4" C 3 part union		2.27		10' 3/4" Copper tubing @.3666	3.67
5	x 4 Patch		5.00		1 3/4" C Corp Cock	4.64
2	hrs. Trucking @.75		1.50		1 3/4" C Curb Cock	6.03
			67.37		1 Box & Rod	5.00
					1 hr. Trucking @.75	.75
						23.15
				5-26-59	Repaired leak by curb	
					Bill sent 5-4-59	17.37

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....